



October 3, 2013

Page 1 of 1

---

## **NovAtel Inc. Announces SPAN on OEMV and SPAN-CPT Firmware Releases SPAN3.912 and CPT3.912**

NovAtel Inc. is pleased to announce the release of SPAN3.912 and CPT3.912 firmware for SPAN OEMV2, OEMV3 and ProPakV3 products, and CPT3.912 for SPAN-CPT on OEMV product. This is a maintenance release primarily to address the following fixes:

- General bug fixes including vehicle body rotation being saved after multiple resets and better handling of flow control signals
- Increased heading covariance for LM20 up to 5 degrees before INS solution reaches a status of INS\_SOLUTION\_NOT\_GOOD
- GPGGA and GPRMC messages are now populated through prolonged GNSS outages

NovAtel is committed to providing excellent value to our customers in the form of firmware updates and upgrades. By providing this functionality as a firmware update, customers can apply it to their existing receivers, enabling quick changeover and now downtime. This firmware update is available for free of charge to all customers.

**For more information on NovAtel products and latest firmware, please contact your local sales representative. A complete list of NovAtel dealers is available at**

**<http://www.novatel.com/where-to-buy/dealers/>**